





Polyarc® v2.0 Troubleshooting Guide

Follow these instructions to troubleshoot a **Polyarc®** that is not functioning properly.
For additional assistance – call 612-787-2721 or email contact@activatedresearch.com

Polyarc® v2.0 reactors are suitable for use with:
Agilent 8890, 7890, 7820, 6890, 5890
Shimadzu 2030
Thermo Fisher, Varian, Bruker, Scion, and more.

 Ask about our **reactor recycling program**

Symptom	Possible Problems	Potential Solutions
<p>FID won't light</p> 	<ul style="list-style-type: none"> Insufficient or Excessive hydrogen or air flow Deteriorated FID jet Too much air going through the Polyarc® Faulty ignitor coil Backflow 	<p>Do NOT check hydrogen and air flow TO the Polyarc® while it is HOT. Your results WILL NOT BE accurate!</p> <ul style="list-style-type: none"> Check the hydrogen and air flow rates going to the FID. The Polyarc® supplies 35 sccm* of hydrogen to the FID, so the actual flow directly to the FID should be reduced to 1.5 sccm* or less Air flow to the Polyarc® should be less than 3 sccm* Remove the Polyarc® to see if the FID will light without it Check the condition of the jet and replace if necessary. Consider purchasing a silicon treated jet Inspect and replace ignitor coil if necessary Check fittings for leaks to ensure there is no backflow <p>*Refer to the Polyarc® installation manual for more details</p>
<p>High quantification error</p> 	<ul style="list-style-type: none"> Sample degradation Inlet discrimination Catalyst deactivation 	<ul style="list-style-type: none"> Test a fresh sample A dirty inlet can result in the preferential absorption, or vaporization, of certain compounds. Inspect and replace/clean the inlet and related parts if necessary Remove the first 6" of the capillary column Your reactor may have reached the end of its useful life. Contact ARC to purchase a replacement Polyarc® reactor
<p>No signal</p> 	<ul style="list-style-type: none"> Leak in a fitting or septa Insufficient pressure in inlet Faulty FID Catalyst deactivation 	<ul style="list-style-type: none"> Test the system for leaks. Replace the inlet septa if necessary The Polyarc® adds a pressure drop to the FID which can lead to lower column flow rates than are reported by the GC at a given inlet pressure. Increase the inlet pressure by a factor of two (2) Test the FID without the Polyarc® Your reactor may have reached the end of its useful life. It's possible the second stage catalyst is irreversibly oxidized, especially if the reactor was exposed to air without adequate hydrogen flow rates. Contact ARC to purchase a replacement Polyarc® reactor

Symptom	Possible Problems	Potential Solutions
<p data-bbox="226 164 327 191">Other</p> 	<p data-bbox="493 164 1104 188">For other GC problems – please refer to the following resources:</p> <p data-bbox="493 212 800 261">Activated Research Company Polyarc® Installation Guide</p> <p data-bbox="493 310 573 334">Agilent GC Troubleshooting Guides: http://www.agilent.com/search/?N=900015658&Ntt=troubleshooting+guides GC Troubleshooting Video Series: http://www.agilent.com/en-us/products/gas-chromatography/troubleshootingvideos</p> <p data-bbox="493 493 569 518">Restek Troubleshooting Guides: http://www.restek.com/en/pages/support-and-troubleshooting/?term=troubleshooting GC Troubleshooting Poster: http://www.restek.com/pdfs/GNWC1723-UNV.pdf</p> <p data-bbox="493 677 737 701">LCGC CHROMacademy GC Troubleshooting and Training Courses: http://www.chromacademy.com/channels/gc-training-courses/troubleshooting/</p>	